

Box 152 May-Jun 1888

Mint of the United States at Philadelphia,

June 22nd, 1888

Hon. Daniel W. Fox,

Superintendent

Dear Sir,

In obedience to your request I have examined the Engine Room, relative to the excessive heat complained of by the Chief Engineer, and find the temperature is as stated by him to be as high as 119 degrees.

There can be no question that steps should ~~not~~ be taken as soon as possible to overcome the difficulty, and afford relief not only to the Engine Room, but also to the rooms adjoining the same, into which this excessive heat is being driven,

I would suggest that ^{an} Exhaust Fan

be introduced to remove the heated air
from the building, this would seem
to be the most practical method to
accomplish the desired end,

Very Respectfully
Sam Jones
Minister

NARA RG104, Entry 1, Box 152

Mint of the United States at Philadelphia,
June 22, 1888

Hon. Daniel M. Fox,
Superintendent

Dear Sir,

In obedience to your request I have examined the Engine Room, relative to the excessive heat complained of by the Chief Engineer, and find the temperature is as stated by him to be as high as 119 degrees.

There can be no question that steps should be taken as soon as possible to overcome the difficulty, and afford relief not only to the Engine Room, but also to the rooms adjoining the same; into which this excessive heat is being driven.

I would suggest that an exhaust fan be introduced to remove the heated air from the building, this would seem to be the most practical method to accomplish the desired end.

Very Respectfully,
Saml. James
Machinist